PEMS 11281

U.S. DEPARTMENT OF LABOR Occupational Safety and Health Administration

Form Approved OMB No. 44-R1387

AUG 2 9 1980

MATERIAL SAFETY DATA SHEET

Required under USDL Safety and Health Regulations for Ship Repairing, Shipbuilding, and Shipbreaking (29 CFR 1915, 1916, 1917)

			g (20 0.11 /0.0) 10					
SECTION I								
MANUFACTURER'S NAME					NO.			
PEMACO INC. (213) 581-718				•				
ADDRESS (Number, Street, City, State, and ZIP Coa 5989 District Blvd. May	le) VWO	od, Ca	a. 90270					
CHEMICAL NAME AND SYNONYMS UI1				11281 SYN	ONYMS			
Petroleum Oil plus addity	7 0 S		FORMULA		:			
TOTTO: Cam OII DIGG SAGIOVES								
SECTION II - HAZARDOUS INGREDIENTS								
PAINTS, PRESERVATIVES, & SOLVENTS	%	TLV (Units)	ALLOYS AND N	METALLIC COA	ATINGS	%	TLV (Units)	
PIGMENTS		•	BASE METAL					
CATALYST			ALLOYS	· \				
VEHICLE			METALLIC COATING	s .				
SOLVENTS			FILLER METAL PLUS COATING OR C	ORE FLUX			······································	
ADDITIVES ,			OTHERS					
OTHERS			•					
HAZARDOUS MIXTURES	OF (THER LIC	UIDS, SOLIDS, OR GA	ASES		%	TLV (Units)	
		•						
				·				
		 					- '	
						1		
. SECT	rior	VIII - P	HYSICAL DATA					
BOILING POINT (°F.)		:	SPECIFIC GRAVITY	(H ₂ O=1)		- 0	,930	
VAPOR PRESSURE (mm Hg.)			PERCENT, VOLATILI BY VOLUME (%)	Ē .	•			
VAPOR DENSITY (AIR=1)			EVAPORATION RAT					
satuality but readily	emi	usifie	d to form [#] So	luble Of	il Emuls	101	า''	
APPEARANCE AND ODOR Clear brown								
		- AND E	XPLOSION HAZA			ı	Uel	
FLASH POINT (Method used) 310°F (PMCC) FLAMMABLE LIMITS N'A								
Dry chemical type preferred								
special fire fighting procedures none special								
•								
unusual fire and explosion hazards none unusual								
			····					

	SECTION V - HE	ALTH HAZARD	DATA	
THRESHOLD LIMIT VALUE No OSHA exposur	re or threshold	limits have	been	established
EFFECTS OF OVEREXPOSURE Slight irritati	ion to eyes and	skin	:	
Skin-remove by	PROCEDURES wiping followed	by washing	with	soap and water
	copious amounts		:	41 1

		SEC	CTION VI - REACTIVITY DATA	
STABILITY	UN	STABLE	CONDITIONS TO AVOID	
	ST	ABLE X		
INCOMPATABIL	ITY (Mat	erials to avoid)		
HAZARDOUS DE	ЕСОМРО	SITION PRODUCTS		
HAZARDOUS MAY OCCUR		MAY OCCUR	CONDITIONS TO AVOID	
POLYMERIZATION	WILL NOT OCCU	R X		
		<u> </u>		

, SECTION VII - SPILL OR LEAK PROCEDURES
STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED Absorb with clay, diatomaceous earth or other inert material
WASTE DISPOSAL METHOD Dispose with plant oil wastes or by controlled burning in
compliance with local regulations

	SECTION VIII - SPECIAL PR	ROTECTION INFORMATION	
RESPIRATORY PI	ROTECTION (Specify type)		
VENTILATION	as required if mist is	generated SPECIAL	
	MECHANICAL (General)	OTHER	
, PROTECTIVE GLO	Rubber gloves	EYE PROTECTION Approved goggles or safety glas	ses
OTHER PROTECT	IVE EQUIPMENT		

SECTION IX - SPECIAL PRECAUTIONS	
PRESAUTIONS TO BE TAKEN IN HANDLING BELOW TOOF	
	 -
OTHER PRECAUTIONS Avoid prolonged breathing of mist	
Avoid prolonged or repeated skin contact	

GPO 934-110

PAGE (2)